



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 1 -- Catchment Information**

Subwatershed: Bear Branch

Location of Catchment Centroid on ADC Map: Year: 2001 Page: 4 Grid: E5

State Plane Coordinates of Outfall Location: X: 1351200 Y: 519000

Closest Road Intersection to Outfall: Cherry Lane

Outfall SDI ID or Outfall Description: Several outfall points along edge of Laurel Lake

Objective: Demonstration / Impairment(s) (Sheet 1) Demonstration, Water Quality

Drainage Area (ac): 6.1 Impervious Area (ac): 3.4

Percent Impervious: 57% Soil Recharge Factor (S): 0.079

WQ<sub>v</sub> (required): 0.286 Re<sub>v</sub> (required): 0.023

Predominant Land Use: Office Buildings Mean Depth to Ground Water: n/a

Sanitary System:  Septic  Municipal Sewer Water Supply:  On Site Well  Public Water

**Storm Drainage System Within Catchment**

Piped: 100% Open Channels: \_\_\_\_\_

Area Drained by System: 100%

Location in Catchment:  Headwaters  Middle  Lower  All

Open Channel Lining- Vegetation: \_\_\_\_\_ Riprap: \_\_\_\_\_ Concrete: \_\_\_\_\_ Other: \_\_\_\_\_

**Existing IMP(s) / BMP(s)**

SDI ID: 85127A Type (number from Sheets 4 & 5): 16 Age: 17

Closest Road Intersection to IMP / BMP: Laurel PI & Cherry La

Catchment Area Treated (ac) : 2.37 Percentage Catchment Treated: 39%

WQ<sub>v</sub> Provided:  YES  NO Re<sub>v</sub> Provided:  YES  NO C<sub>p</sub> Provided:  YES  NO

SDI ID: \_\_\_\_\_ Type (number from Sheets 4 & 5): \_\_\_\_\_ Age: \_\_\_\_\_

Closest Road Intersection to IMP / BMP: \_\_\_\_\_

Catchment Area Treated (ac) : \_\_\_\_\_ Percentage Catchment Treated: \_\_\_\_\_

WQ<sub>v</sub> Provided:  YES  NO Re<sub>v</sub> Provided:  YES  NO C<sub>p</sub> Provided:  YES  NO

SDI ID: \_\_\_\_\_ Type (number from Sheets 4 & 5): \_\_\_\_\_ Age: \_\_\_\_\_

Closest Road Intersection to IMP / BMP: \_\_\_\_\_

Catchment Area Treated (ac) : \_\_\_\_\_ Percentage Catchment Treated: \_\_\_\_\_

WQ<sub>v</sub> Provided:  YES  NO Re<sub>v</sub> Provided:  YES  NO C<sub>p</sub> Provided:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 1 -- Catchment Information (concluded)**

<b>CATCHMENT SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.14</u>	Re <sub>v</sub> (provided) :	<u>0.01</u>
Area Treated (ac):	<u>2.37</u>	Impervious Area Treated (ac):	<u>1.68</u>
Area Treated (%):	<u>39%</u>	Impervious Area Treated (%):	<u>49%</u>

**Comments**

---



---



---



---



---



---



---



---



---



---

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information**

Site Name: Laurel Lakes Executive Park Address: 8301-8387 Cherry Lane

Site Owner: \_\_\_\_\_

State Plane Coordinates of Site Centroid: X: 1351200 Y: 519000 Date: 5/9/03

Personnel: PM, SM Weather: overcast, rain, 70F deg

Area (ac): 5.3 Impervious Area (ac): 3.4

Percent Impervious: 63% Soil Recharge Factor (S): 0.075

WQ<sub>v</sub> (required): 0.274 Re<sub>v</sub> (required): 0.021

Property Area (ac): 5.3 Property Area Included in Site: 100%

Amount of Catchment Occupied by Site: 87%

**Storm Drainage System Within Site**

Piped: 95% Open Channels: 5% Area Drained by System: 100%

Open Channel Lining - Vegetation: 0% Riprap: 0% Concrete: 0% Other: 0%

**Existing IMP(s) / BMP(s)** (Identified on Page 1, FORM 1, Catchment Information)

SDI ID: \_\_\_\_\_ Condition:  Excellent  Good  Average  Fair  Poor

SDI ID: \_\_\_\_\_ Condition:  Excellent  Good  Average  Fair  Poor

SDI ID: \_\_\_\_\_ Condition:  Excellent  Good  Average  Fair  Poor

**Site Information**

Type of Pavement:  Bituminous  Concrete  Gravel  Grid Pavers  Other \_\_\_\_\_

Pavement Condition:  Excellent  Good  Average  Fair  Poor

Underdrains can be easily directed to existing storm drains or daylighted:  YES  NO

Gutter/Exterior Downspouts Present:  YES  NO

Roof Connected Directly to Storm Drain:  YES  NO

Roof Drains onto Impervious Surface:  YES  NO

Obvious Existing Drainage Problems:  Extensive  Moderate  Average  Limited  None

Steep Slopes Present:  Extensive  Moderate  Average  Limited  None

Existing Landscaping:  Extensive  Moderate  Average  Limited  None

Mature / Specimen Trees:  Extensive  Moderate  Average  Limited  None

Area Available for Aboveground BMPs:  Extensive  Moderate  Average  Limited  None

Existing Cover of Potential Aboveground BMP Locations:  Grass  Landscaped  Gravel  Other Pervious  
 Pavement  Other Impervious

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information (concluded)**

**Commercial / Institutional**

Islands Present:  YES  NO                      Curb Present Around Island:  YES  NO

Ground Level of Island Relative to Pavement:  Above  Equal  Below

Island Landscaping:  Impervious  Bare Earth  Gravel  Grass  Mulch  Herbaceous Plants  Shrubs  
 Trees (<2 in. DBH)  Trees (2 - 6 in. DBH)  Trees (>6 in. DBH)

Trees have sufficient spacing to allow IMPs  YES  NO

Parking area that can be directed to potential treatment area with little grading: 100%

SITE SUMMARY			
WQ <sub>v</sub> (provided) :	<u>0.14</u>	Re <sub>v</sub> (provided):	<u>0.02</u>
Area Treated (ac) :	<u>2.37</u>	Impervious Area Treated (ac):	<u>1.68</u>
Area Treated (%) :	<u>45%</u>	Impervious Area Treated (%):	<u>49%</u>

**Photographs**

No. <u>723</u>	Description: <u>looking north along west side of site</u>
No. <u>724</u>	Description: <u>looking east along south side of site</u>
No. <u>725</u>	Description: <u>looking east across center of site</u>
No. <u>726</u>	Description: <u>looking south along west side of site</u>
No. <u>727</u>	Description: <u>looking east along north side of site</u>
No. <u>728</u>	Description: <u>looking west along north side of site</u>
No. <u>729</u>	Description: <u>looking south along east side of site</u>
No. <u>730</u>	Description: <u>looking west along south side of site</u>
No. <u>731</u>	Description: <u>looking north along east side of site</u>
No. _____	Description: _____

**Comments** Some buildings have downspouts draining directly to conveyance. They can be easily disconnected. Some potential IMP sites are landscaped.

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information**



723



724



725



726



727



728

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information (concluded)**



729



730



731

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 5

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.56 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



844



845

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 45

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.56 ac 100%

**Retrofit of Existing SWM BMP**

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



844



845

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 59

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 3, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.29 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



846



847

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 52

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 3, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.29 ac 100%

**Retrofit of Existing SWM BMP**

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



846



847

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.49 ac 100%

**Retrofit of Existing SWM BMP**

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.019</u>	Re <sub>v</sub> (provided):	<u>0.002</u>
Area Treated (ac):	<u>0.49</u>	Impervious Area Treated (ac):	<u>0.23</u>

**Photographs**

No. <u>848</u>	Description: <u>looking west</u>
No. <u>849</u>	Description: <u>looking east</u>
No. _____	Description: _____

**Comments** IMP treat 34% of the drainage area  
IMP size = 1,664 sq ft  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



848



849

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: \_\_\_\_\_ ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.005</u>	Re <sub>v</sub> (provided):	<u>0.001</u>
Area Treated (ac):	<u>0.09</u>	Impervious Area Treated (ac):	<u>0.07</u>

**Photographs**

No. <u>850</u>	Description: <u>looking south (photo taken 5/19/03)</u>
No. <u>851</u>	Description: <u>looking north (photo taken 5/19/03)</u>
No. _____	Description: _____

**Comments**

IMP size = 638 sq ft

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



850



851

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: \_\_\_\_\_ ac 90%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



848



849



852



853

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: \_\_\_\_\_ ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.013</u>	Re <sub>v</sub> (provided):	<u>0.000</u>
Area Treated (ac):	<u>0.24</u>	Impervious Area Treated (ac):	<u>0.08</u>

**Photographs**

No. <u>856</u>	Description: <u>looking north</u>
No. <u>857</u>	Description: <u>looking south</u>
No. _____	Description: _____

**Comments** IMP treat 60% of the drainage area  
IMP size = 1,111 sq ft  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



856



857

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.09 ac 100%

**Retrofit of Existing SWM BMP**

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.006</u>	Re <sub>v</sub> (provided):	<u>0.000</u>
Area Treated (ac):	<u>0.09</u>	Impervious Area Treated (ac):	<u>0.08</u>

**Photographs**

No. <u>858</u>	Description: <u>looking south</u>
No. <u>859</u>	Description: <u>looking north</u>
No. _____	Description: _____

**Comments** IMP treat 34% of the drainage area  
IMP size = 554 sq ft  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



858



859

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.07 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



860

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 39

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.19 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.011</u>	Re <sub>v</sub> (provided):	<u>0.001</u>
Area Treated (ac):	<u>0.19</u>	Impervious Area Treated (ac):	<u>0.14</u>

**Photographs**

No. <u>861</u>	Description: <u>looking west</u>
No. <u>862</u>	Description: <u>looking east</u>
No. _____	Description: _____

**Comments** IMP treats 24% of the drainage area  
IMP size = 966 sq ft  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



861



862

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 38

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.28 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.018</u>	Re <sub>v</sub> (provided):	<u>0.001</u>
Area Treated (ac):	<u>0.28</u>	Impervious Area Treated (ac):	<u>0.23</u>

**Photographs**

No. <u>863</u>	Description: <u>looking north</u>
No. <u>864</u>	Description: <u>looking south</u>
No. _____	Description: _____

**Comments**

IMP size = 2,107 sq ft

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



863



864

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 38

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.11 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.008</u>	Re <sub>v</sub> (provided):	<u>0.000</u>
Area Treated (ac):	<u>0.11</u>	Impervious Area Treated (ac):	<u>0.10</u>

**Photographs**

No. <u>865</u>	Description: <u>looking north</u>
No. <u>866</u>	Description: <u>looking south</u>
No. _____	Description: _____

**Comments**

IMP size = 762 sq ft

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



865



866

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 38

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.09 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.006</u>	Re <sub>v</sub> (provided):	<u>0.000</u>
Area Treated (ac):	<u>0.09</u>	Impervious Area Treated (ac):	<u>0.07</u>

**Photographs**

No. <u>867</u>	Description: <u>looking northeast</u>
No. <u>868</u>	Description: <u>looking southwest</u>
No. _____	Description: _____

**Comments** IMP treats 29% of the drainage area  
IMP size = 517 sq ft  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



867



868

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 3 -- Opportunities and Constraints of Potential Management Practice

New LID IMP  SWM BMP Retrofit  New SWM BMP  Type (Sheets 4 & 5): 38

State Plane Coordinates of IMP / BMP Centroid: X: \_\_\_\_\_ Y: \_\_\_\_\_

Sketch Location of Footprint (with Approximate Dimensions) and Drainage Boundary on Site Map

Identify all Impairments Addressed by Recommendation (Sheet 1): 1, 2, 3, 4, 7, 16

Treatment Area Ownership:  Transportation ROW  Utility ROW  County  Other Government  Private  
 Other \_\_\_\_\_

Infrastructure / Structures / Buildings Impacted:  YES  NO

Limited Impact to Adjacent Properties:  YES  NO

Area Accessible for Construction:  YES  NO

Area Accessible for Maintenance:  YES  NO

Limited Permitting Issues:  YES  NO

Jurisdictional Wetlands Impacted:  YES  NO

Forest Retention Area Impacted:  YES  NO

Conservation Easement Impacted:  YES  NO

Utilities Present:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Utilities Impacted:  None  Natural Gas  Electric  Telephone  Cable  Water  Sewer  Other \_\_\_\_\_

Impacted Utilities:  Above Gound  Underground

Critical Area Impacted:  YES  NO

Mature / Specimen Trees Impacted:  YES  NO

Existing Landscaping Impacted:  YES  NO

Underdrain Needed:  YES  NO

Underdrains Can Discharge:  YES  NO

Soils are Suitable:  YES  NO

Ground Water Table Level Suitable:  YES  NO

Estimate IMP / BMP drainage area included on site: 0.35 ac 100%

### Retrofit of Existing SWM BMP

SDI ID: \_\_\_\_\_

Add Forebay:  YES  NO

Modify Outlet Structure:  YES  NO

Add Aquatic Bench:  YES  NO

Grade Bottom of Facility:  YES  NO

Plant Native Vegetation:  YES  NO

Provide Additional Storage Volume:  YES  NO

Excavation / Raise the Embankment:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice (concluded)**

<b>IMP / BMP SUMMARY</b>			
WQ <sub>v</sub> (provided):	<u>0.024</u>	Re <sub>v</sub> (provided):	<u>0.001</u>
Area Treated (ac):	<u>0.35</u>	Impervious Area Treated (ac):	<u>0.30</u>

**Photographs**

No. <u>869</u>	Description: <u>looking west</u>
No. <u>870</u>	Description: <u>looking east</u>
No. _____	Description: _____

**Comments** Affects sculpture.

IMP treats 95% of the drainage area

IMP size = 2,103 sq ft

---



---



---



---



---



---

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 3 -- Opportunities and Constraints of Potential Management Practice**



869



870